


NO.4950 Knot Remover



A set capable of easily regenerating dead knots and missing knots.
Available from 5mm – 25mm.



- ① Shave with a taper drill along the diameter of the knot.
- ② Shave with a wooden plug under a branch a little thicker than the hole of the knot.
- ③ Drive a wooden plug coated with a bonding agent into the hole made in the knot with a taper drill.
- ④ Cut off the projecting part of the wooden plug, plane sand finish to it, and it will turn into a beautiful live knot instantly.




Unit mm

	Shank-Dia
Set	
Taper Drill	10
Dowel Cutter	10

NO.82 Double Spur Drill



The screw point is made of High Speed Steel and is replaceable.
Long tool life is ensured.
Wood chip ejection is quite smooth because of the Teflon Coated process.



Tungsten Carbide Tips

S=Size O/A=Overall Length T/L=Twist Length SD=Shank-Dia

Unit mm

Size	O/A Length	Twist Length	Shank-Dia	Size	O/A Length	Twist Length	Shank-Dia
12	350	280	10	19	350	280	12
13	350	280	10	20	350	280	12
15	350	280	12	21	350	280	12
16	350	280	12	22	350	280	12
18	350	280	12	24	350	280	12

