


## 外形図

### ■HH-100AS (最適把持力 2000N~5000N)

#### HH-100AS 標準



### ■HH-150AS (最適把持力 5000N~12000N)

#### HH-150AS 標準

