



 mm				 mm	 kg daN	
<b>500x7,5</b>	2.500	100	<input type="checkbox"/>	20÷145	65	<b>SEL.2.436</b>
			<input checked="" type="checkbox"/>	20÷145	65	<b>SEL.3.436</b>
	1.000	100	<input type="checkbox"/>	20÷145	65	<b>SEL.2.436R</b>
			<input checked="" type="checkbox"/>	20÷145	65	<b>SEL.3.436R</b>
<b>540x7,5</b>	2.500	100	<input type="checkbox"/>	20÷160	65	<b>SEL.2.437</b>
			<input checked="" type="checkbox"/>	20÷160	65	<b>SEL.3.437</b>
	1.000	100	<input type="checkbox"/>	20÷160	65	<b>SEL.2.437R</b>
			<input checked="" type="checkbox"/>	20÷160	65	<b>SEL.3.437R</b>
<b>750x7,5</b>	1.500	100	<input type="checkbox"/>	32÷222	65	<b>SEL.2.441</b>
			<input checked="" type="checkbox"/>	32÷222	65	<b>SEL.3.441</b>
	700	100	<input type="checkbox"/>	32÷222	65	<b>SEL.2.441R</b>
			<input checked="" type="checkbox"/>	32÷222	65	<b>SEL.3.441R</b>
<b>430x9</b>	2.000	100	<input type="checkbox"/>	20 ÷ 118	80	<b>SEL.2.144</b>
			<input checked="" type="checkbox"/>	20 ÷ 118	80	<b>SEL.3.144</b>
	1.000	100	<input type="checkbox"/>	20 ÷ 118	80	<b>SEL.2.144R</b>
			<input checked="" type="checkbox"/>	20 ÷ 118	80	<b>SEL.3.144R</b>
<b>550x9</b>	1.500	100	<input type="checkbox"/>	20÷160	80	<b>SEL.2.142</b>
			<input checked="" type="checkbox"/>	20÷160	80	<b>SEL.3.142</b>
	700	100	<input type="checkbox"/>	20÷160	80	<b>SEL.2.142R</b>
			<input checked="" type="checkbox"/>	20÷160	80	<b>SEL.3.142R</b>
<b>780x9</b>	1.000	100	<input type="checkbox"/>	20÷235	80	<b>SEL.2.143</b>
			<input checked="" type="checkbox"/>	20÷235	80	<b>SEL.3.143</b>
	500	100	<input type="checkbox"/>	20÷235	80	<b>SEL.2.143R</b>
			<input checked="" type="checkbox"/>	20÷235	80	<b>SEL.3.143R</b>
<b>920x9</b>	1.000	100	<input type="checkbox"/>	40÷280	80	<b>SEL.2.154</b>
			<input checked="" type="checkbox"/>	40÷280	80	<b>SEL.3.154</b>
	500	100	<input type="checkbox"/>	40÷280	80	<b>SEL.2.154R</b>
			<input checked="" type="checkbox"/>	40÷280	80	<b>SEL.3.154R</b>