

Endless belts for air belt sander

**No. CB12** Ceramic Endless Belt  
(for GT-BS12)



Model No.	Size	Grit No.	Quantity	EDP No.
<b>CB12-60</b>	12mm×330mm	#60	50	350061
<b>CB12-80</b>	12mm×330mm	#80	50	350062
<b>CB12-120</b>	12mm×330mm	#120	50	350064

**No. ZB20** Zirconia Endless Belt  
(for GT-BS12)



Model No.	Size	Grit No.	Quantity	EDP No.
<b>ZB20-40</b>	20mm×520mm	#40	20	350067
<b>ZB20-60</b>	20mm×520mm	#60	20	350068
<b>ZB20-80</b>	20mm×520mm	#80	20	350069

**Air Disk Sander Wheel (For DS50A)** See P190 One point→

**No. PD-P60** Pitatto Disk Paper



**No. PD-P6** Pitatto Holder



Model No.	Grit No.	Max. Circumferential Speed (rpm)	Material	Use	Quantity	EDP No.
<b>PD-P60</b>	Z60	20,000	Zirconia	Thin pressed plate deburring, surfacing, etc.	50	350111
<b>PD-P6</b>	—	—	Rubber (Pad)	For Pitatto disk paper	1	350116

**Wheels to Remove Rust / Stains (For DS50B)** See P190 One point→

**No. HMW10** Hammer Wheel



Model No.	Max. Circumferential Speed (rpm)	Material	Use	Quantity	EDP No.
<b>HMW10</b>	5,000	SUS	Slag and spatter removal after welding, etc.	1	350121